2 NAME(S) OF STRUCTURE		INVENT	National Park Service Pacific Northwest Region Cultural Resources Division			Westin Building, R 1920 2001 Sixth Avenu Seattle, Washington 98121				
.(CARD	1 of 2)	5 ORIGINAL USE	7. CLASSI	IFICATION					3 RATING	
South Puyallup River Bridge		Vehicular Bridge							10 DATE	
3 SITE ADDRESS (STREET & NO)		6 PRESENT USE		,					1931	
West Side Road crossing the South Fork Puyallup River	Same	8. UTM Z	ONE EASTING		NORTHING			11. REGION		
4. CITY/VICINITY COUN Nisqually Entrance Pier		STATE ashington	SCALE	1:24 OTHER	1:62.5	_	JUAD JAME			
12. OWNER/ADMIN ADDRESS			L	OTHER		···	JAME			
NPS/Mount Rainier National P	ark, Tahoma Wo	ods-Star Route, As	hford,	WA 98304						
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSIMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.					AND					
Reinforced concrete, otheres-cente	red(filled)arc	ch with stone masor	ry faci	ing; one spa	n concre	te abut	ments (faced	with	
stone); stone parapet walls and										
The South Puyallup River Bridge										
to build a road along the park's										
drafted by the National Park Ser route was carried out in August										


An early report stated that the construction of a road over Ipsut Pass would be excessively costly. NPS Director Mather approved the recommendation for studying alternative routes from the north. Meanwhile, the BPR survey party was transferred to the south end of the proposed route. Beginning at the Nisqually Road junction (near Tahoma Creek), the road centerline was located northward to Round Pass and the South Puyallup River. By December 1925, 13 miles of road from the

14 CONDITION STATE STATE

16. SIGNIFICANCE

Nisqually Road to Klapatchee Ridge was surveyed.

The South Puyallup River Bridge was completed in 1931 as part of the West Side Road construction. Originally planned to link the Nisqually entrance with the Carbon River Entrance, the West Side Road was first in 1925-26. The project, carried out over a ten-year period beginning in 1926, was never wholly completed. The South Puyallup River Bridge is typical of the reinforced concrete arch bridges built in the park in the twenties and thirties, and rustically styled with native stone.



Bridge Safety Inspection Report, South Fork Puyallup River Bridge, prepared by U.S. DOT, FHWA (Denver, CO.), 8/27/79 Maintenance Division, Mount Rainier National Park

Superintendent's Monthly Reports, 5 September 1925, 5 October 1925, 5 December 1925, 7 January 1926, 6 October 1926, 4 November 1926, 4 January 1927, 5 November 1928, 4 November 1930, 5 October 1931, Archives, Mount Rainier National Park

Original Drawing, "South Puyallup River Bridge", 2 sheets, recommended by T. C. Vint, NPS, 3/15/30, (MORA DRG. NO. 923)

Robert N. McIntyre, "Short History of Mount Rainier National Park", unpublished manuscript, 1952, Archives, Mount Rainier National Park, p.246 and p.260

Robert L. Carper, "List of Classified Structures Inventory", NPS Report, Denver Service Center, 1976

22. INVENTORIED BY Gray Fitzsimons	MORA Cultural Resource Survey	DATE 9/12/82
	<u> </u>	<u> </u>

PNF '7 6/82	<u> </u>	г т			 	1	1	Ţ	ר	IN VENT	ORY	Pacific No	Park Service orthwest Region esources Division	20	001 9	Buildin Sixth A	lvenu	1920 n 98121
2 NAME(S) OF STRUCTURE	1				<u> </u>	J	<u> </u>	1	Ш	5. ORIGINAL USE		SIFICATION	,			1 1	111910	9. RATING
		(CA	RD 2	2 of	2)											$\bot \bot$		
South Puya	llup F	≀iver	Bri	.dge						Vehicular Bridge						11	-	10 DATE
3. SITE ADDRESS (STREET & NO)				6. PRESENT USE	1 —			·	_ _	+		1						
												,				<u> </u>	<u> </u>	1931
West Side South Fork			_							Same	1	ZONE EAST	TING N	ORTHING	T	$\overline{}$	1889	11. REGION
	ruyaı	.rup .		COUNT										$\bot\bot$			27	
CITY/VICINITY Nisqually				ier					[4] =	STATE Shington	SCALE	1:24 OTHER:	1:62.5		QUAD			
OWNER/ADMIN ADDRESS	Entran	ice		Ter							!	OTHER:_	<u> </u>		NAME		===	
	Painic	ar Na	tion	al '	Dar	k.	Tab	10m	аW	oods-Star Route, A	\shfor	1. WA 983	04					
										AL DIMENSIONS, MATERIALS, MAJOR								
The project had a tour of the r	the e oute, land,	enthu: Cram	sias nton	tic exp	su res	ppo sed	rt l h.	of is	Su des	perintendent O.A. ire to see the roa acceptance of bids	Tomliad comp	nson and C pleted at	ongressman Lo an early date	. Un	ider	the a	auspi	ces of
Nisqually Road tion work progr reported at the Twenty-nine per	juncti ressed e end o rcent o	ion to at a of 19 of the	o Ro in ex 127, ie wo	ound ktre "poo ork l	Pa mel or has	ss. y s man	lov age	Cle V p eme co	ari ace nt mpl	was awarded the ong and grading work. Superintendent is responsible for eted to date where on of the West Signal	th common the common t	menced in nson, much contractor eventy-nin	1926. Over t discouraged being so far e percent sho	the newith behiculd b	ext f the .nd i be fi	ive y entir n his nishe	ears re op wor ed at	, construction, k schedu this ti

XSX XXXXXXXXXXXXXXX

14 CONDITION

completed the following summer in August 1930.

GOOD

FAIR

☐ EXCELLENT

The South Puyallup River Bridge, comprised of a reinforced concrete, filled arch, measures 42'-0" in length. It has a total width of 34'-10" and accommodates two lanes of traffic (the roadway measures 27'-0" curb-to-curb). Native stones used in facing the spandrel walls were laid in a rubble masonry fashion to affect a more rustic appearance. The parapet walls lining the bridge were built in a similar style.

PRUINS

15. DANGER OF DEMOLITION? (SPECIFY THREAT) **□YES**

□NO

Finally on July 4, 1930, the road was opened to Round Pass. Construction then began on the South Puyallup River and Saint Andrews Creek Bridges. Mr. E.A. Davidson of the Landscape Engineers Office and field supervisor for all landscape matters regarding the West Side Road construction was in charge of the stone work for the bridges. Both spans were

DETERIORATED

Although further clearing for the West Side Road was carried out from Klapatchee Ridge to Sunset Park, exhaustion of funds precluded further construction beyond the North Puyallup River. After the 1930s, no further attempt was made to

(over)

UNKNOWN

17 PHOTOS AND SKETCH MAP OF LOCATION		· · · · · · · · · · · · · · · · · · ·		
omplete the two-lane, gravel surfaced roadway. I	t is currently opened in the s	i ummer between	Nisqually Road and	
Klapatchee Ridge. (See entry of St. Andrews Creek	Pridge)	diffice becaucer	the of the state of the state of	
Klapatchee kluge. (See entry of St. Andrews Creek	Bridge.	, '	1	ψÌ
				£
·				3
				e^{i}
			A CALL TO SERVICE AND ADDRESS OF THE PARTY O	
			30 B	ء .
		Will said	1 1 1 1 - 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	. 7
	•			
				1
•			THE PROPERTY OF THE PARTY OF TH	4
				3
				Ä,
		3		3
		Service Service		S
		(5.87)		Ž.
			13 17 6 2	. Ś
				1
•		Total Control of the		
				€.
				-
				7
				٠.
		20		4
		به است و	a breve	7
		n ,, 72/		ď
				•
18. LOCATED IN AN HISTORIC DISTRICT?				
19 PUBLIC ACCESSIBILITY YES, LIMITED YES, UNLIMITED	20. EXISTING NA NHL H. SURVEYS COUNTY LOCAL	ABS HAER-1	HAER NPS STATE	
□ NO □ □ UNKNOWN	20. EXISTING NA NHL H. SURVEYS COUNTY LOCAL			
21. REFERENCES—HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER	1			
·				
		•		
22. INVENTORIED BY	AFFILIATION		DATE	

÷

4.